

FILM EDIT LOG

PROJECT: MADIGAN HOSPITAL, FT LEWIS AVG. ENDLAP: 60% & 80%
IDENT. #: S 88058 AVG. SIDELAP: 32%
DATE FLOWN: 7/9/88 PARALLAX CHECK: _____

LINE	2	3	4	5	6	7	8	9	10	11	12	13	14	15	REMARKS
1	62	62	60												2700 AMT
1	82	81	81	81	80										{
2	60	62	60												
2	60	60	60												2100 AMT
2	77	82	82	82	79	82	80								{
2	80	81	80	79	80	79	81								
1	80	80	79	80	80	79	80	79							
1	58	61	60	61											

1) Check line against flight map and mark every 5th exposure on map.
2) Endlap shall not be less than 55% nor more than 65%.
3) Sidelap shall not be less than 20% nor more than 40%.
4) Crab shall not exceed 3%.
5) Tilt shall not exceed 3% nor shall it exceed 5% between successive exposures.
Average tilt over the project shall not exceed 1%.
6) Identify strip and exposure with grease pencil. X-out excess exposures.
7) Annotate each line and exposure in ink on North or West edge.

RECORDED BY: EGGER 7/12/1988
REVIEWED BY: HONSEL 7/12/1988

Figure 4-8. Film edit log (from US Army Engineer District, Seattle)